Eshe Eiles

INSTRUCTION MANUAL

Check Weighing Scales

FS-6Ki

FS-15K*i*

FS-30K*i*



This Manual and Marks

All safety messages are identified by the following, "WARNING" or "CAUTION", of ANSI Z535.4 (American National Standard Institute: Product Safety Signs and Labels). The meanings are as follows:

MARNING	A potentially hazardous situation which, if not avoided, could result in death or serious injury.
 CAUTION	A potentially hazardous situation which, if not avoided, may result in minor or moderate injury.



This is a hazard alert mark.

Note This manual is subject to change without notice at any time to improve the product. No part of this manual may be photocopied, reproduced, or translated into another language without the prior written consent of the A&D Company.

Product specifications are subject to change without any obligation on the part of the manufacture.

Copyright©2006 A&D Company, Limited

Contents

1. COMPLIANCE	2
2. INTRODUCTION	3
3. UNPACKING	3
4. CAUTION	4
4-1. Precautions for Installing the Scale	4
4-2. Precautions for Operating the Scale	4
4-3. Precautions for Storing the Scale	4
5. SETTING UP	5
5-1. Attaching a display pod to the display support column	5
5-2. Installing the scale	5
6. NAMES AND FUNCTIONS	6
7. BASIC OPERATION	
7-1. Turning the power ON and OFF	10
7-2. Selecting a weighing unit	10
7-3. Basic operation	
7-4. Weighing with Preset Tare	11
7-5. To Clear a Tare Weight	11
7-6. Weight display resolution	12
7-7. Simplified operation mode	12
7-8. LCD backlight	12
8. CHECK WEIGHING	13
8-1. Target weight setting mode	13
8-2. Upper & Lower limits weight setting mode	16
8-3. The comparator memory	17
9. ANALOG SWEEP DISPLAY	
9-1. Selecting a display mode	19
9-2. Example of the analog sweep display	20
10. CALIBRATION	
10-1. Calibration using a weight	22
10-2. Gravity acceleration correction	23
11. FUNCTIONS	24
11-1. The procedure for setting parameters	
11-2. Function list	
12. SPECIFICATIONS	27
12-1. Specifications	27
12-2. Dimensions	28
13. GRAVITY ACCELERATION MAP	29

1. COMPLIANCE

Compliance with FCC rules

2. INTRODUCTION

This manual describes how this scale works and how to get the most out of it in terms of performance.

FS-i series check weighing scales have the following features:

4. CAUTION


4-1. Precautions for Installing the Scale


5. SETTING UP

5-1. Attaching a display pod to the display support column

- 1. Take out whole of the scale from the box taking care not to pull the load cell cable.
- 2. Remove 2 clamps and 2 M4x12 screws.
- 3. Attach the display pod to the display support column and tighten the M4x12 screws removed at step 2.
- 4. Attach the clamps and tighten them after tilting the display pod where you like to use.

6. NAMES AND FUNCTIONS





(1) WEIGHT DATA DISPLAY.

This display shows the weight on the weighing pan.

(2) WEIGHING UNIT INDICATOR.

This display area shows the weighing unit in use.

(3) ANALOG WEIGHT DISPLAY.

This scale has a 60 segments analog sweep display representing zero to full scale when the simple weighing mode display is selected. In the limit check weighing display mode, this display shows comparison limits and results.

(4) OVER RANGE INDICATORS.

This mark comes ON when the weight is outside the range of analog sweep display..

(5) COMPARISON INDICATORS.

The indicators LO (RED), OK (GREEN) and HI (YELLOW) show the results of the weight comparison.

(6) STABLE ANNUNCIATOR.

This annunciator will come ON when the weight reading is STABLE.

7 ZERO ANNUNCIATOR.

This annunciator will come ON when the scale is showing the center of ZERO.

(8) NET ANNUNCIATOR.

This annunciator will come ON when the scale is displaying the NET weight on the weighing pan.

9 PT ANNUNCIATOR.

This annunciator will come ON when the scale is displaying the preset tare weight.

(10) PRINT ANNUNCIATOR.

This annunciator will come ON for a moment when the scale sends out the weight data by pressing the PRINT key or auto-printing.

(11) PRECAUTION AGAINST LOW BATTERY.

This annunciator will come ON when the optional battery is getting close to low battery.

(12) KEYPAD.

A 13 key pad provides control and number keys.

Description of Key Operations

ON OFF

ON/OFF Key

The ON/OFF key turn the power on or off. When turned on, the scale will be automatically set to zero (power-on zero).

± ZERO

ZERO / ± Key

The ZERO key zeros the scale when the weight is stable (STABLE annunciator ON). In the data entry sequence this key switches the sign "+" and "-".

TARE

TARE Key

The TARE key switches the scale to net weight mode and zeros the weight display when the weight is plus and stable. The ZERO and NET annunciators will come ON.

РТ

PT Key

The PT key is used to enter a tare weight via the 10-key pad.

SAMPLE

SAMPLE / 9 Key

The SAMPLE key will register the sample weight as the target. In the data entry sequence this key displays the number 9.

KEY

KEY / 8 Key

The KEY key allows you to enter a target weight using the keypad. In the data entry sequence this key displays the number 8.

7 RECALL

RECALL / 7 Kev

The RECALL key is used to recall target weight and/or HI/LO limits. In the data entry sequence this key displays the number 7.

HI

HI / 6 Key

The HI key allows you to enter the comparator HI limit using the numeric keypad. In the data entry sequence this key displays the number 6.

L0

LO / 5 Key

The LO key allows you to enter the comparator LO limit using the numeric keypad. In the data entry sequence this key displays the number 5.

STORE	STORE / 4 Key The STORE key is used to store target weight and/or HI/LO limits. In the data entry sequence this key displays the number 4.
DISP.	DISP. / 3 Key When the DISP. key is pressed the analog weight display steps through the 4 available modes of simple weighing, target weighing, limit check weighing and display off. In the data entry sequence this key displays the number 3.
UNITS	UNITS / 1 Key The UNITS key is used to select the desired weighing unit . In the data entry sequence this key displays the number 1.
PRINT ENT	PRINT / ENT Key The PRINT key is used when the serial data option OP-03 or OP-04 is installed and sends one data string. In the data entry sequence this key is used to ENTER the numeric data into the scale memory.
C	C Key The C key is used to clear an incorrect data entry from the numeric keys.
0	O and 2 Keys These keys are used to display the number 0 or 2 during a data entry sequence.

7. BASIC OPERATION

7-1. Turning the power ON and OFF

1. Press the ON/OFF key to turn the power ON.
All the display symbols are displayed and the scale waits for the weighing data to become stable.

After the weighing value internally becomes stable, the display turns off for a moment and zero is shown with the ZERO annunciator (power-on zero). If the weighing value is unstable, the display will continue to "88888888". Check if anything touches the weighing pan, or check if there is strong wind or vibration.

The range for power-on zero is within ±50% of the weighing capacity (kg) around the calibrated zero point.

If the power is switched ON while there is a load beyond this range, the scale shows "----". Remove the load on the weighing pan.

2. Pressing the ON/OFF key again, and the power will be switched OFF.

Note for the Legal for Trade Models

7-6. Weight display resolution

The FS-*i* series has three kinds of weight display resolution, NORMAL, HIGH and HIGHER. The following is about "kg" and "lb" display for reference. See the "12. SPECIFICATIONS" in detail.

NORMAL: 1/3,000

HIGH: $1/6,000 \sim 1/7,500$ (depending on capacity) HIGHER: $1/12,000 \sim 1/15,000$ (depending on capacity)

The factory setting is the NORMAL resolution, but it is possible to change by Function "F2". Set this function according to the application.

8. CHECK WEIGHING

The FS-*i* series provides for easy check weighing of products. There are two comparison modes according to number of parameters to set, "Target weight setting mode" and "Upper & lower limits weight setting mode". The comparator results are indicated by HI (yellow), OK (green) or LO (red) lights on the display. The results are also audible by the buzzer inside the scale.

The analog sweep display will help to see where the weight is in the OK range or how far from the OK range. See "19. ANALOG SWEEP DISPLAY" in detail.

If the optional OP-03 or OP-04 is installed, comparator relay output is also available.

Setting the target weight by sample

- 1. Press the ZERO key to zero the weight display if necessary.
- 2. Place the sample on the weighing pan. The display shows the sample item's weight.
- 3. Press the SAMPLE key. The sample weight flashes and the central part of analog display turns on.

- 3. Press the ENT key to store the HI limit weight in memory.
- 4. The display shows 5t or ed for a few seconds and returns to weighing mode.
- 5. Press the LO key. Then, the last LO limit weight entered will flash and the left part of analog display turns on.
- 6. Enter the LO limit weight via the 10-key pad.

5.	Press the	LO	key.	Then,	the	last	LO	%	weight
	entered will	flash	and	the lef	t par	t of	anal	og	display
	turns on.								

6. Enter the LO limit weight via the 10-key pad.

- 3. Press the ENT key to store the HI limit weight in memory.
- 4. The display shows 5t or ed for a few seconds and returns to weighing mode.
- 5. Press the LO key and the last LO limit weight entered will flash.
- 6. Enter the LO limit weight via the 10-key pad.

Recalling a set of limits from memory

- 1. Press the \fbox{RECALL} key. Then the display will show $\fbox{r d 00}$.
- 2. Press the memory number, for example 3.

9. ANALOG SWEEP DISPLAY

The FS-*i* series has a 60 segments analog sweep display. The DISP. key switches its display mode.

9-2. Example of the analog sweep display

Simple weighing display mode

FS-30Ki / d=0.01 kg
TARGET WEIGHT SETTING MODE
(F07-1 or F07-2)
Target weight = 15.00 kg.
Net weight display (tare entered)


FS-30Ki / d=0.01 kg UPPER & LOWER LIMIT WEIGHT SETTING MODE (F07-0)

Target weighing display mode

FS-30Ki / d=0.01 kg TARGET WEIGHT SETTING MODE (F07-1 or F07-2) Target weight = 15.00 kg. FS-30Ki / d=0.01 kg UPPER & LOWER LIMIT WEIGHT SETTING MODE (F07-0) Target weight = 5.00 kg. HI = 10.10 kg, LO = 9.91 kg

10. CALIBRATION

This function adjusts the scale for accurate weighing. Calibrate the scale in the following cases.



11. FUNCTIONS

The scale has Function settings to expand your applications.

The parameters set in the Function settings are maintained even if the power switched off.

11-1. The procedure for setting parameters

- 1. Turn the power off.
- 2. Press and hold the ZERO key and turn the power on via the ON/OFF key. Then the fist function number is displayed.
- 3. Enter the Function number using the 10-ley pad.
- 4. Press the ENT key. Then the parameter stored is appears.
- 3. Enter the parameter value using the 10-ley pad.

11-2. Function list

Item Function number Description

Item	Function number	Description	
	f 11- 0		

12. SPECIFICATIONS


12-1. Specifications

	MODEL	FS-6Ki	FS-15K <i>i</i>	FS-30K <i>i</i>		
	Capacity	6	15	30		
kg		0.002 *	0.005 *	0.01 *		
	Min. display	0.001	0.002	0.005		
		0.0005	0.001	0.002		
	Capacity	6000	15000	30000		
a		2 *	5 *	10 *		
g	Min. display	1	2	5		
		0.5	1	2		
	Capacity	15	35	70		
lb		0.005 *	0.01 *	0.02 *		
10	Min. display	0.002	0.005	0.01		
		0.001	0.002	0.005		
	Capacity	240	560	1120		
oz		0.1 *	0.2 *	0.5 *		
02	Min. display	0.05	0.1	0.2		
		0.02	0.05	0.1		
lb-oz	Capacity	15	35	70		
10-02	Min. display	0.1	0.1	0.1		
Repeatability (Std. deviation)		0.001 kg	0.002 kg	0.005 kg		
Lineari	ity error	±0.002 kg	±0.005 kg	±0.01 kg		
Span c	drift	±20	ppm / °C (5°C~35°C)	/ 41°F~95°F)		
Displa	у		nent LCD display (Character height 18.6 mm) with backlight 60 segment analog sweep display with backlight			
Displa	y update					
Operating temp10°C~40°C / 14°F~104°F, less tha			ss than 85% R.H.			
	supply	AC main (100V~240V) or SLA Battery (option)				
Weighing pan size			1 / 9.8 x 9.8 in.	380 x 300 mm 15.0 x 11.8 in.		
Dimension		250(W) x 414(E 9.8(W) x 16.3(I	D) x 496(H) mm D) x 19.5(H) in.	380(W) x 464(D) x 496(H) mm 15.0(W) x 18.3(D) x 19.5(H) in.		
Weight (approximately)		8.1 kg /17.9 lb		14.9 kg / 32.8 lb		
Calibration weight		6 kg 15 lb	15 kg 30 lb	30 kg 60 lb		


^{*)} Factory setting

12-2. Dimensions

FS-6K*i* FS-15K*i*



FS-30K*i*





Unit: mm

13. GRAVITY ACCELERATION MAP

Values of gravity at various locations

Amsterdam Athens Auckland NZ Bangkok Birmingham Brussels Buenos Aires Calcutta Cape Town Chicago Copenhagen Cyprus Djakarta Frankfurt Glasgow Havana Helsinki Kuwait Lisbon London (Greenwich)	9.813 m/s ² 9.807 m/s ² 9.799 m/s ² 9.783 m/s ² 9.813 m/s ² 9.811 m/s ² 9.797 m/s ² 9.788 m/s ² 9.796 m/s ² 9.815 m/s ² 9.797 m/s ² 9.810 m/s ² 9.816 m/s ² 9.819 m/s ² 9.819 m/s ² 9.812 m/s ² 9.812 m/s ² 9.796 m/s ²
Los Angeles	9.796 m/s^2
Madrid	9.800 m/s ²





MEMO

_	

MEMO

_	



A&D Company, Limited

3-23-14 Higashi-Ikebukuro, Toshima-ku, Tokyo 170-0013 JAPAN Telephone: [81] (3) 5391-6132 Fax: [81] (3) 5391-6148

A&D ENGINEERING, INC.

1555, McCandless Drive, Milpitas, CA. 95035 U.S.A. Telephone: [1] (408) 263-5333 Fax: [1] (408)263-0119

A&D INSTRUMENTS LTD.

Unit 24/26 Blacklands Way, Abingdon Business Park, Abingdon, Oxon OX14 1DY United Kingdom Telephone: [44] (1235) 550420 Fax: [44] (1235) 550485

<German Scales Office>

Große Straße 13 b 22926 Ahrensburg GERMANY Telephone: [49] (0) 4102 459230 Fax:[49] (0) 4102 459231

A&D MERCURY PTY. LTD.

32 Dew Street, Thebarton, South Australia 5031 AUSTRALIA Telephone: [61] (8) 8301-8100 Fax: [61] (8) 8352-7409

A&D KOREA Limited

8th Floor, Manhattan Bldg. 36-2 Yoido-dong, Youngdeungpo-ku, Seoul, KOREA Telephone: [82] (2) 780-4101 Fax: [82] (2) 782-4280